

BUILDING SAFETY CERTIFICATE

Dated: 19/9/2024

It is certified that the existing building North East Global School, Dhubri, Assam name of the building or premises) at Jhagrarpar Pt: III, Magurmari, Behind Dhubri Civil Hospital, P.O: Jhargarpar, Dist: Dhubri, Assam, Pin:783331 (address) is having block(s)/Floor(s) as per details below:

Block	Block	Block	Block	Block	Block
(1)	(2)	(3)	(4)	(5)	(6)
Four					
	(1)	(1) (2)	(1) (2) (3)	(1) (2) (3) (4)	(1) (2) (3) (4) (5)

The building is owned/occupied by North East Global School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Executive/ Assistant Executive Engineer/ Asstt. Engineer, PWD, Dhubri District Territorial Building Division, Dhubri (Name of Department/ Govt.) on 02/07/2024 (date inspection) presence of Abu Taher Ali, Principal of North East Global School, Dhubri, in (name and addresses of the Manager/Secretary or his representative) and that the Assam building/premises is fit for occupancy for running school with effect from 02/07/2024 for a period of 1 (One) years in accordance with rule and subject to compliance of the specific conditions as appended.

4

Visited the school building found that or or or lot leady & found that we when the school boulding is should weather the school boulding is should weather the school boulding is should weather when the school boulding is should weather the school boulding is should be school boulding.

Signature with Seal : Executive Singineer PWD

Name : Dhubri District Territorial
Building Division Dhubri

Designation:

Name & Address of Department/ Office:

Assistant Engineer, PWD. Dhubri District Territorial Building Division, Dhubri.

^{2.}

^{3.}

^{*} Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.